





NOTICE!!!

Please read the instructions fully before assembly. These instructions include important information which could ensure correct assembly.




1  X2	2  X2	3  X1	4  X1	A  M6X35mm X4
B  M6X12mm X4	C  M6X60mm X8	D  M4 X1		




STEP1 :

A X4	C X8	D X1
		
M6X35mm	M6X60mm	M4




STEP2:

B X4	D X1
	
M6X12mm	M4







STEP3:




NOTICE!!!

Please read the instructions fully before assembly. These instructions include important information which could ensure correct assembly.




1  X4	2  X4	3  X8	4  X4	5  X4
6  X4	A  M6X30mm X32	B  M6X35mm X20	C  M6X25mm X16	D  M4 X1



X4

STEP1 :


B X20	D X1
	
M6X35mm	M4



X4

STEP2:


C X16	D X1
	
M6X25mm	M4



X4

STEP3:


A X16	D X1
	
M6X30mm	M4



X4


STEP4:

A X16	D X1
	
M6X30mm	M4



X4

STEP5:



X4